

## Black Diamond Equipment Issues Recall for Recon LT Avalanche Transceiver



For North America, visit [here](#).

For Europe, visit [here](#).

For the rest of the world, [contact the local distributor](#).

SALT LAKE CITY, UT (February 14, 2025) – Black Diamond Equipment<sup>®</sup> is recalling the Black Diamond Recon LT avalanche transceiver and related avalanche safety sets due to a corrosion issue that may cause it to malfunction. Recon LT owners can have their transceiver repaired, exchanged for a different model, or refunded.

In some cases, the metal contact of the Recon LT's switch mechanism may corrode. If this occurs, the device could malfunction or turn off, potentially hindering avalanche rescue efforts and increasing the risk of serious injury or death. Consumers who own the Black Diamond Recon LT should immediately stop using it and follow the recall procedures.

To date, Black Diamond has received six consumer reports related to this issue, with no injuries, accidents, or fatalities. Black Diamond is committed to addressing this matter swiftly and proactively.

The Consumer Product Safety Commission (CPSC) has been notified.



## Affected Products

This recall affects all Black Diamond Recon LT transceivers manufactured and sold between June 1, 2021 - February 14, 2025, with serial numbers starting with the range 2040 - 2321. The serial number can be found by connecting your transceiver to the PIEPS app via Bluetooth.

This transceiver was sold as a standalone unit and as part of two avalanche safety sets. The Product Names, Style Numbers, and SKUs are below:

Product Name	Style Number	SKU	Serial No. Begins with:
BD RECON LT BEACON	BD151007	BD1510070000ALL1	2040 - 2321
BD ALPINE AVY SAFETY SET	BD151010	BD1510100000ALL1	2040 - 2321
BD RECON LT AVY SAFETY SET	BD151011	BD1510110000ALL1	2040 - 2321

## Recall Procedures

Owners of Black Diamond Recon LT avalanche transceivers should immediately stop using them and follow the recall procedures. Consumers in North America and Europe have three options:

- **Send your device back to Black Diamond for rework:** We will replace your Recon LT's switch contact with a corrosion-resistant stainless-steel version. Upon receiving your device, our team will replace the contact, conduct a full inspection, and return it within 14 business days. Shipping both ways is free of charge.
- **Exchange for a different model:** Swap your Recon LT for a Black Diamond Guide BT or the Recon X. Shipping both ways is free of charge (quantities permitting).
- **Request a full refund:** If preferred, you may return your device for a full refund. Shipping is free of charge.

For other countries, please [contact](#) your local distributor.

**For more information, including an FAQ, and to start the recall process, visit this [webpage](#).**

For questions about the Recon LT avalanche transceiver recall, contact Black Diamond at 1-866-306-0865 (Mon-Friday, 9 a.m.- 4 p.m. MT) or email [2025reconltrecall@bdel.com](mailto:2025reconltrecall@bdel.com).